TE	TOTAL TIME IN SERVICE				AUTHORI CERT 8
	HOURS	10ths			

10/17/2024 Tach:3400.3 TSMOH:1097.6 ETT:1887.3
Completed 100hr inspection IAW FAR 43 Appendix D
Changed oil and oil filter and serviced engine with 12qts
Phillips 20W50 oil, test ran for leaks, none noted.
#1 74/80 #2 72/80 #3 60/80 #4 74/80 #5 76/80 #6 76/80
Installed new bracket induction air filter.
The aircraft and/or components were repaired and inspected in accordance with the current rules of the Federal Aviation Regulations and was Airworthy for return to service only for the work performed.

Steve Hoppes A&P 3504760