


From: [Dan Jay](#)
To: [Dan Jay](#)
Subject: 206 log Eng 2
Date: Thursday, September 19, 2024 4:32:22 PM



DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations
6-27 19 95				Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)



WALKER FIELD
GRAND JUNCTION, CO 81506
(303) 243-7900

NR 8439G
S/N 248629R
TTAF 2302.7
Component ENGINE

MFG Continental
WO#1 38385 WO#2
TTE 729.7

Model TS10-520-M6
Date 06/27/1995 TACH 2302.7
TSMOH 00.0

FAA CERTIFIED REPAIR STATION
WTXR173J

Reinstalled this engine s/n 248629R on N8439G, Cessna U20603990. SEP 95-6 Engine fuel hoses inspection/replacement C/W by installing new hoses. Reinstalled wastegate p/n 470908-9011 s/n MLR0151 after O/H. Reinstalled relief valve p/n 470944-12 s/n F10138 after O/H. Reinstalled prop governor p/n C290D4C/T2 s/n 770953 after O/H. Reinstalled controller p/n 470688-7 s/n 6A0102 after O/H. Installed 12 qts Aeroshell 30W mineral oil. Run up and leak checked OK.

Signature *[Handwritten Signature]*
WEST STAR AVIATION, INC.
Grand Junction, CO.
CRS No. WTXR173J

[Handwritten Note]
INSPECTION & WAS FOUND TO BE
DIRTY. *[Handwritten Signature]*

WEST STAR AVIATION
ENGINE DIVISION

MFG.: CONTINENTAL

MODEL: TSIO-520-M

2856 Aviators Way
Grand Junction, CO.
(800) 255-4193

S/N: 248629-R

W/O: #5942E

DATE: 6/22/95

Gold Star zero time equivalent engine per Continental manual X30575A
Engine and accessories were remanufactured to factory new tolerances.

See back section for a list of AD notes and manufacturers service bulletins that were complied with.

Total previous time: 729.7 Hrs.

Time since overhaul: Test Cell.

The engine and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details are on file at this agency under Work Order #5942E dated 6/22/95.

Signature

[Signature]
WEST STAR AVIATION, INC.

Grand Junction, Colorado

CRS NO. WTXR173J

All applicable engine bulletins through this date 6/22/95 checked for compliance. This engine was run in a test cell.

Warranty number:

002352

Warranty start date:

7/1/95

RECORDED
TACH
TIME

374

72

with 10
engine and ten down
wash A.P. 654

DATE 5-16
19 96.

RECORDING
TACH
TIME

TODAYS
FLIGHT

TOTAL
TIME IN
SERVICE

Description of Inspections, Tests, Repairs and Alterations
Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

5-16. 2374 72 Changed engine oil & filter. Filled with 12 qts Shell 15W/50. Ran engine and leak check. Safetied filter. Wash down engine and cowling. J. H. Hressey A.P. 554976809.

REPLACED BRACKET AIR FILTER ELEMENT. J. H. Hressey A.P. 554976809

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations <small>Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)</small>
19 96				
8-16	24175	SMOH	114.8	100HR INSPECTION CLEAN & GAP PLUGS - COMPRESSION #1 74/80 #2 74/80 #3 72/80 #4 72/80 #5 74/80 #6 74/80 - CHANGE OIL & FILTER 12 QTS SHELL 15W50 - CHECK EX SYSTEM & PRESSURE TEST. CHECK MAG TIMING CHECK AIR FILTER & FUEL SCREEN. DRESS PROP - CHECK TURBO - DRESS PROP BLADES - RND DP CHECK OK - I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN 100HR INSPECTION & WAS FOUND TO BE AIRWORTHY. <i>James J. Talbot</i> RRP 14700027
12/03/97		TACH	2525.8	TSMH 223.1 TT 952.8 STARTED LOG # 3

Sent from my iPhone