
From: Dan Jay
To: Dan Jay
Subject: Logs Engine

Date: Tuesday, July 23, 2024 10:42:47 AM




ENGINE MAINTENANCE RECORDS	7
Log No	
Engine Manufacturer LYCOMING Model AEID-360-HIA Serial No. L-77527-51A RL-11294-51A Date installed on aircraft 83495 10-1-99 Time Between Overhauls (TBO) 2000 Hours	
If used on multi-engine aircraft:	

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK		
				TOTALS brought forward from previous page		
5/9/96	36.18	36,18	1516.58	Changed oil & serviced with		
				aeroshell 100. Inspected + cleared		li co
				oil screen. Washed engine o		1
				ground run check good.		
				R & M AIRCRAFT SPECIALTIES INC.		
				2642 Airport Dr., Ste. 101 N. Las Vegas, NV. 89030		
				FAA Approved Repair Station #SYVR693K		
6/21/96	44.41	-	1524.81	Inspected o cleaned oil screen, cleaned		
				+ gapped spark plags. Congression 1-72/80, 2-76/80, 3-74/80, 4-76/80. Cherred		
		i Val			0	0
				fuel injectors, washed engine +		
				ground run chech good.		
				INSPECTION AND WAS DETERMINED TO BE		

6/21/46	44.41	-	1524.81	Inspected + cleaned oil screen, Cleaned
				+ gapped spark plugs. Compression 1-72/80, 2-74/80, 3-74/80, 4-76/80. Chancel
			4	fuel injectors, Washed engine +
-				ground run chech good.
				INSPECTION AND WAS DETERMINED TO BE
-				Orie P. Hulle
				R & M AIRCRAFT SPECIALTIES INC. 2642 Airport Dr., Ste. 101 N. Las Vegas, NV. 89030 FAA Approved Repair Station
	-			I SYVR693K
1 6	1/21/16 44.	41	1584	injector fuel lines
		-		B&M AIRCRAFT SPECIALTIES ING.
L	-			SUB-TOTALS this page N. Las Vegas, NV 89030 FAA Approved Repair Station TOTALS—Carry forward to next page #SYN/R693K

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
		OIL IN FIRE		TOTALS brought forward from previous page
7-17-96	1548,82	Anna?	Pette	CHAMICE ON CLASMED SCREEN, SERVICED
			505.0	WITH & ars Agassian WIOD, WARPED
	1223	E 04	Maria	ENGINA, RUN-UP: LANK CLE PARTOSMAA.
				Donnel B Many
				AP585840607
9-20-96	1575.3		S 45	I certify that this ENCINE has been inspected in
120		The same		accordance with CO. O HA Inspection and was determined to be in airworthy condition.
				Date 9-20-96 Tech Time 19745.3
	10000	33000		SMOH: 94,9 Total Time
				Inspectors Signature Chartolle Son
	HILLIE	5) 1000-10		Certification No. 47454228047
	BANK			W
87	TP CIA	TACH	1 1600	+
-Jest	NIVOZ	21- \$	874	(DIAN SCIOTA) WITH AFTER 1000-50;
			. 72-	
Cer	52 0	1000) (Oz	TURN TO SEVICE
		201		Jeff Farmer A&P557926049





Magon Ale TIME TO	OTAL TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
28 MAR 97 TE	4ett 1657	TOTALS brought forward from previous page
CHANGE OU	& CUEA	U SCITERU WITH APPRO 100W-50
CUSSE CONTRE	DES 70510	URN TO SERVICE OF CAN
		Soft Farmer A #P 357026049
16 JUNE 97	TACH IN	5
CHANGE OU &	CUEAN S	COSSIN WITH ASSU 1000-50; COULT
		Cours CHECK #1-76 #2-76 #3-77 #4-8
Curse contras	2; 600a	The # TOSTUPE TO STRUKE
SOFE ALS LOGG FOR		Uate 6-16-17 Tach 165 mon 215 I certify this ENGUE has been inspected in accordance with the manufactures ADDIAN inspection criteria and have found it to be in anwardly inspection criteria and have found it to be in anwardly inspection applicable. Altworthiness Directives thru
		91-12 have been compiled with.

			Inspection criteria and have found it to be in airworthy
		Manager of	Gondition. Applicable Airworthiness Directives thru
			Joff Falmer IASS PRESSET
	10 50 100	9000	000
7-7-97	228.31 228.31	17087	0 1 //
	0.71	1100.1	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
			overhauled starter, part # MZ4222 ECH
200	9 S / 5 S .	March 1	5n# A118775, see yellow tay
16599	BUT BUT		attached above.
	MARINE STATE		ops / ok
SHOW THE	TO SECURE		Ray TOKES AP 534761613
-			
Den.		11. 30	
7.28.9	7239.96239.9	6 1720.56	Change of & cleared SCROEN
111 74			Sorviced with DS 100-50 WT
THE STATE OF			8 978. Repaired garce Gran Cestr
			They flows ATP (03249H)
			SUB-TOTALS this page
	S STANDARD	- Calar	
		MAN SERVICE STREET	TOTALS—Carry forward to next page
Secretary of			
BREE	THE REAL PROPERTY.		

ATE	TOTAL TIME IN	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
	SERVICE	OVERNAUL	Time	TOTALS brought forward from previous page
2597	1747,		1747,	Sourced with 05-100/500T Pursell A 20 A+P 422-04-8069
				Sourced with DS-100 / JULT
				Pursell A 20 A+P 423-04-8069
		HOBBS		
2/10/97			1750.75	REMOVED AND REINSTALLED OIL
				Cooler. RAN Eng, ckd for leaks
	1	1		and ops. SEE Attached yellow
				ACE AVA. PP. Kaisten, 560 76 9424
1	1			ACE AVA. pr. Kaislen, 360 16 7877
	1			
1	1	1		
1		1		

33 -2		TO	TALS brought forward from	
		101	TALS brought forward from previous page	
				7.
1334	RONIL	/coming		
		Journing	TLRED-489	
652 Olive			(Rev. 10-96)	
Williams	port, PA 17701	U.S.A.		
This en	gine has bee	n overhauled/rebuil	t in accordance with the applicable Textron Lycoming manu-	000
			ministration Airworthiness Directives and Textron Lycoming	
airwork	thy to return	to service. All acces	with. All parts have been inspected and have been determined ssories as part of the type certificate are either new or newly	
			T001 for applicable accessory part numbers and serial num-	
bers.	uled. Refer	to enclosed Form E	T001 for applicable accessory part numbers and serial num-	
overhabers. Engin Serial	e Model:	to enclosed Form E	T001 for applicable accessory part numbers and serial num- Authorized Signature S. F. Ell. Textron Lycoming	
overhabers. Engin Serial Total	e Model: #: Time:	AEIO-360-H1A RL-11294-51A 0.0	Authorized Signature S. F. LLL Textron Lycoming 652 Oliver Street	
overhabers. Engin Serial Total Work	e Model: #: Time: Order #:	AEIO-360-H1A RL-11294-51A 0.0 29926	Authorized Signature S. F. LLL Textron Lycoming 652 Oliver Street Williamsport, PA 17701	
overhabers. Engin Serial Total Work	e Model: #: Time:	AEIO-360-H1A RL-11294-51A 0.0	Authorized Signature S. F. LLL Textron Lycoming 652 Oliver Street	
overhabers. Engin Serial Total Work	e Model: #: Time: Order #:	AEIO-360-H1A RL-11294-51A 0.0 29926	Authorized Signature S. F. LLL Textron Lycoming 652 Oliver Street Williamsport, PA 17701	
overhabers. Engin Serial Total Work	e Model: #: Time: Order #:	AEIO-360-H1A RL-11294-51A 0.0 29926	Authorized Signature S. F. LLL Textron Lycoming 652 Oliver Street Williamsport, PA 17701	
overhabers. Engin Serial Total Work	e Model: #: Time: Order #:	AEIO-360-H1A RL-11294-51A 0.0 29926	Authorized Signature S. F. LLL Textron Lycoming 652 Oliver Street Williamsport, PA 17701	
overhabers. Engin Serial Total Work	e Model: #: Time: Order #:	AEIO-360-H1A RL-11294-51A 0.0 29926	Authorized Signature S. F. LLL Textron Lycoming 652 Oliver Street Williamsport, PA 17701	
overhabers. Engin Serial Total Work	e Model: #: Time: Order #:	AEIO-360-H1A RL-11294-51A 0.0 29926	Authorized Signature S. F. LLL Textron Lycoming 652 Oliver Street Williamsport, PA 17701	





ATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
			State of the last	TOTALS brought forward from previous page
N.Y	NORTH	FIELD AVIA	ATION, HAN	IGER L908, OAKLAND AIRPORT, OAKLAND CA 94621
X	AIRCRA	FT: N5058L		NEW YORK THE PARTY OF THE PARTY
7.4		october 1,19		4 F A/O TT: 4750 00 Facility 0
Inspeted in	acordance with	Decathalon Servi	ce Manual table 3	1.5, A/C TT: 1753.20, Engine: 0. 3-1, Inspection Report, 1000 hr. section of and full scope and detail of FAR 43 appendix
D.				hell 100, straight mineral oil.
Engine gro	und run per Lyce	oming Service Ins	truction No. 1427	B. section 1 A&B
Oil suction	screen and filte	r checked for cont	tamination, found	none.
Operation	al check satisfac			
Recomme Copy of La	end engine insper ecoming Service	ction and oil chan	ge no later than 1:	853.20 tach. wher for flight break in proceedures.
				TED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS BEEN
	ET THAT THE		BEEN INSPEC	
ICERT			DETERMINED	TO BE IN AIRWORTHY CONDITION.
ICERT			DETERMINED	TO BE IN AIRWORTHY CONDITION.
		555045849	DETERMINED	TO BE IN AIRWORTHY CONDITION. Ruhard K. Roeles 10/1/89
Richa	rd K Dodge	555045849	A&P / IA	Ruhard K. Roeles 10/1/89
Richa	rd K Dodge	555045849	A&P / IA	Ruhard K. Cooles 10/1/89
Richa	rd K Dodge	555045849 25 CHANGE	A&P/IA	Ruharch K. Cools 10/1/99 - CLEMED THE SCREEN, SHEW 80 PKH. Coclails STEELING
Richar 10/25/9	9 1759.	555045849 25 CHANGE ONG	A&P/IA THE O	CLEANED THE SCREEN, SHEW 80 Phily Coclaile STHERE CLEANED THE SCREEN, SHEW 80 Phily Coclaile STHERE CLEANES SCREEN, SHEW 80 Phily Coclaile STHERE
Richar 0/25/9	9 1759.	555045849 25 CHANGE ONG	A&P/IA THE O	CLEANED THE SCREEN, SHEW 80 Phth Coclaile SHEWARD COMPRESSION AUSSISTED
Richar 0/25/9	9 1759.	555045849 25 CHANGE ONG	A&P/IA THE O	CLEANED THE SCREEN, SHELL 80 Phth Coclails SHELLE CLEANED THE SCREEN, SHELL 80 Phth Coclails SHELLE Cleaned Screen, Sources in and 80. compression which is appeared plugs. a Goodat ALGSSTSTON DAVIS AIR REPAIR, INC.
Richar 10/25/9	9 1759.	555045849 25 CHANGE ONG	A&P/IA THE O	CLEANED THE SCREEN, SHEW 80 PHY Coclails STEELING CLEANED THE SCREEN, SHEW 80 PHY Coclails STEELING CLEANED SCREEN, SHEW 80 PHY Coclails STEELING CHANGE SCREEN, SHEW 80 PHY Compression TORK A GAPPES PLAGE A GARLET ALGESTSTEEL DAVIS AIR REPAIR, INC. Certify that this Engine has been inspected in accordance
Richar 0/25/9	9 1759.	555045849 25 CHANGE ONG	A&P/IA THE O	CLEANED THE SCREEN, SHEW 80 Phily Coclaile SHEWARD COMPRESSION AUSSIA BOLLONDERS

Signed C Grobet Mo 555501 Signature Aircraft Service LLC 06/04/01 300 County Airport Rd. Vacaville, CA 95688 Tach 1860.44 ACTT TSMOH NA Replaced fuel injector body gaskets and attatching hardware.		certify that this Engine has been inspected in accordance
Signature Aircraft Service LLC 06/04/01 300 County Airport Rd. Vacaville, CA 95688 Tach 1860.44 ACTT TSMOH NA Replaced fuel injector body gaskets and attatching hardware.	1 105397 James	with a 100 hr inspection and determined to be airworthy Tach 1325.6 Date: (1-1-tago Engine 72.4 S.M.O.H. Prop 72.9 S.M.O.H. Total Time My sessel 1633
	1 2	Signature Aircraft Service LLC 06/04/01 00 County Airport Rd. Vacaville, CA 95688
	R	eplaced fuel injector body gaskets and attatching hardware.
Brooks R. Mayes AP 369453224	В	rooks R. Mayes AP 369453224

CE	TIME SINCE OVERHAUL	RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
			TOTALS brought forward from previous page
			N50584 WEST VALLEY AVIATION COUNTY RD. 87B ESPARTO, CA. 95627 ph. (530) 662-8630 DATE 8 / 2 / 0(AIRFRAME -TACH- HOBBS
			PERFORMED DYNAMIC BALANCE OF PROPELLER ASSY. INITIAL READING 21 IPS. ADDED 46 INCH INITIAL READING 08 IPS. ALL GRAMS OF WEIGHT. FINAL READING 08 IPS. ALL WORK DONE IN ACCORDANCE WITH CHADWICK-HELMUTH MANUAL WORK DONE IN ACCORDANCE WITH CHADWICK-HELMUTH MANUAL WORK DONE IN ACCORDANCE WITH CHADWICK-HELMUTH MANUAL PROP, AND BACKPLATES INDEXED TO THE CRANKSHAFT FLANGE TO MAINTAIN PROPER BALANCE WEIGHT POSITION. IF INDEXING IS LOST, REMOVE BALANCE WEIGHTS. SIGNED CHAPTER 1 ASP
			DAVIS AIR REPAIR, INC.
	1000		l certify that this EVENUE has been inspected in accordance

		DAVIS AIR REPAIR, INC.
	1886.1	I certify that this EVENUE has been inspected in accorda
12/1/01 133.2		with a 100HL inspection and determined to be already
CERNED PRICES CHECKED		Tach 18861 Debet (2/1/01
C/WAD. 93-02-03 FIR	INSTECTION LINE	Engine 133-2 SMOH Prop 133-2 SMOH
INSPECTION		Total Time 133-2
Child Edule Art 5266	16047	Mond Philip Codaile No. 526616047
1/23/02	S ENGINE	CHANGED ON- CLERNED SCREED Philip Coloils the P 506616047 THEN 1917-4. 01/9/03
DETERMINED TO BE	AIRWORTH	(WARLE TO WE (SHILL WED) C/W AD. 93-02-0 WHAT THE MAG TIMBLE (SHILL WS) C/W AD. 93-02-0 WHAT THE INSECTION LUE INSPECTION CHECKED COMPRESSION ALL BOOKER APSOED16047
TOTAL TIME 1640	TACH HOBBS	CHECAT FREE INSECTION LIVE INSPECTION CHECKED
Date 1/01/02 Signad		Comparassion, With Eschile Alsocology
	Total Control of the	Contract of the contract of th

		TOTALS brought forw	vard from previous page
	Abo	ove and Beyond Aviation	
	400 S	Smith Ranch Rd. Hangar 8	
	Ph: (415)	San Rafael, CA. 94903)472-4200 fax: (415)472-4;	201
		,	
	Date: 11/17/2003	N5058L	Tach: 1951.91
	Make: Lyc. AEIO-360-H1A	1	Total: 198.51
	Changed oil and checked fil	lter screen. No metal f	found. Serviced engine
	with 6 qts. Aeroshell W100	oil. Ground run good.	. No leaks noted.
	111	011	
	Signature State	1	A&P 572578187 I.A.
	10	~~	7/25/010/ I.A.
	Beyond Aviation I, CA. 94903		400 Smith Ranch Rd. Hangar 8 Ph: (415)472-4200 fax: (415)472-4201
	4.42004	N5058L	Hobbs: 1952.03
20,000,000	/16/2004 Lycoming AEIO-360-H1A	NOUSEL	Total: 198.63
No oil	change done at this time. Ser	viced all spark plugs. S	Serviced all fuel injectors. Compression
Check i	results as follows: #1 76/80 ed fuel screens. Replaced indu	#2 76/80 #3 76/80 #4 action air filter C/W A	4 76/80. Retimed magnetos to engine.
CHCCKC			
	y that this Engine was inspect	ted in accordance with	an annual inspection and was
I certify	ined to be in an airworthy con	ndition.	
I certify determ	/ ////		
determ	TE KANT KRUNT	A&P 5	72578187 I.A.
I certify determ Signate	ire for from	A&P 5	72578187 I.A.

	Signature	Kart	Kymod	A&P 572578187 I.A.
4/22/05			comi	lind the An 2002-26-01 date 0 1/3/103
229.	OTTE	TENE	h, T	spection of fuel INTECTOR (1008
1982.	2 TACH	ITA	for	uspection of fuel INTECTOR LINES security and Routing. Next due 2082.2
			THE	
			Servi	ced 8 gts 100 W AFROSHELL O'L
			comp	NESSION #178/80 #2 79/80 #3 78/80 #479/80
				HAS BEEN INSPECTED IN
				ACCORDANCE WITH A A A A A A A A A A A A A A A A A A A
			1000000	TO BE IN AIRWORTHY CONDITION.
				KYLE K. GABEL
			PostINS	s portion Corond Run & Calles satisfactory
				SUB-TOTALS this page
-				TOTALS—Carry forward to next page

	1	-		Page No
DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
11-16	2006	TAC	4 199	2.74
1)	ADS C	HECK	ED TH	ALE 2006-23
2)	ACCOM	PLISHE	PAD	2-76 -01 EXTERNAL FUEL LINES BYUTSUM
INSI	PECTION	٠.	The said	
3	A DRAZ	WED EN	SERVED	TL, CLEANED YCREEE N, SERVICED WITH SOT
PH	CLIPS	POOAD	oic,	WASHED ENGING, RAN ENGINE AND KEAR
CH	ECKED	. No co	PKS"	B. A BJUSTED OZE PRESSURE TO 63PSTAT
#00	DO RAN	C. AD	JUSTED	FOLERAMTOGSORPM. D. ACCOMPLISHE
Co	MPRES	STON	CHECK.	#17780 #2 1480 #3 79/86 #4 78/80.
	1) SERO	TOEP	LINSPE	TED ENGINE PER SKEAB SERVICE MANUAL
100				CFR 43 APPENDIX D.
				HIS ENGINE HAS BEEN INSPECTED I.A.W.
AN	SANNCE	AG IN	SPECT	ON AND HASBEEN DETERMINED TOBE
IN) ATRW	ORTHY	CONDI	TOW ATTHIS TIME.
L,		,orab	- Joh	invaria Phillips #1858722 AP
17/1/6	9 Teck	1997,9	6 al A	05 C/ 02-26-01. de Corpussion #17/ #27/50

A	CERTI	BY TH	AT TO	IS ENGINE HAS BEEN INSPECTED IAW.
AN AN	NCOAC	INSI	ECTZ	NO AND HASBEEN DETERMINED TOBE
		DTIN C	01117	TOW OTTHIS TIME.
		,otato bo	Soft	would Phillips #1958722AP
7/1/19	Tel	1957.96	1 00	C/602-26-01. L Corpression #17/6 #27/50
SMOH	#375	#47	(D) ()	och for laste I certify starch agin la
241.56				an annual especter a dress determent land
				Reliable AP3280798IA
	arrive	The Co	delen	Jecobe Minister Company
all la		20/12/	205014	Dained al remard & cleaned screen reserved with
Sugo		694.24		
				84 Phillips oil Served spark plugs check ign
				harness varified may timing Comptest #1-42-14
				3-72.4-74/80 and Repaired primer line at culinder.
				replaced filler tube aposket. See A. Ulisting for update.
		2010		I certify that this enque has been insp per an annual
				map & retinized to be in amount this condition.
	100		17 30	SUB-TOTALS this page + Om What 377541403APP, W
				TOTALS—Carry forward to next page

2001	IN SERVICE	SINCE OVERHAUL	METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK DAT
3/27				TOTALS brought forward from previous page
			352.1	Oue Water 9/1/20
8/3/2011	330.4		2083.6	complied with 40 2008-14-07 dated
				8/14/08 by Dws Pection of Luck Invection
				Lines for proper Routing condition
				+ seewity Regulaced #2 Insection
	A CONTRACTOR			Live with vew P/NLW/2088-0-170
				AD west due 2183.6 TACHON 8/2012
-	4			#1 74/80 #2 74/80 #3 78/80 #4 74/80
la contraction of the contractio				Seviced 8 gts Phillips 20w.50
				I certify that this ZNS INC has been inspected In accordance with a(n) ANNAC and found to be in
				An airworthy condition this time and date. Time 2083-6 777 Date 8/3/2011
38.5				KYLE CABEL A&P2885867IA 8/1//3 21
				POST DOSPOETION Grand performance
		10 8 100		Run Latter + 545+enses
				extis factory
1 1 7 2	and Palvier		A cutalist	


DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
1/2012	2101.7	348.5	2101.7	complied with AD 2011-26-04 dated
		pi ed	Cours ke	1/25/12 by Duspection of fuel two edition
				Lives for Routing, security +
				condition. wext due 2201.7 TACH
	-	1		compression test Results
		1000		# 76/80 #1 75/80 #3 78/80 #4 7/80
-				Serviced Egys 20W-50 Phillips Xoil
				I certify that this Engine has been inspected
				In accordance with a(n) ANN GIAC and found to be in An airworthy condition this time and date.
				Time 2101.7 TTA Date 9/1/2012
				KYLE GABEL A&P2885867IA
				Post Ausrection 610 and performance
	and the same			Run & Cate + systems Is satisfactory
8/1/1	3 2117	85 364.6	2117.7	complie from th AD 2011-26-04 Sate 01/25/12

				Time 2101. 7 TTA Date 9/1/2012
1				KYLE GABEL A&P2885867IA
				Post possection 610 and performance
				Run & Coate + systems Is satisfactory
8/1/3	2117.85	364.65	2117.7	conflictorth AD 2011.36-04 date 01/35/12
11.				by Despection of tuel IN Jectionlines for
				Proper Routing, security + condition
				next due 2217.85 TALL
				toppossion test results \$170/80 #270/80 #370/80 #474/80
				#120/80 #3 20/80 #3 20/80 #4 1/80
127				Replaced UALUE COVE gaskets with
				ven Sizicone 681794115
				Serviced 8945 Phillips
				20W-50 xcoil
				t fall
				(A-P)83536)
	7			SUB-TOTALS this page
				TOTALS—Carry forward to next page

				No. of the Control of	
	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME		OF WORK PERFORMED— E NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from pre	vious page
		Teer	tify that this	Eughue hasbon	en inspected
		In ac	cordance w	rith a(n) ANN UN Cand for	and to be in
		An	irworthy co	ondition this time and date.	ink to be id
		Tim	2115	35 TA Date 8/1/201)
			1	9	
-		KY	LE GABEL	A&P2885867IA	
		1		Post #	x section Gian a
	III A	Name .	0.01	20 D	xpoetion Ground
			107	maret kuns los	LUS & SYSTEMOUS
		A Property of	Sat	Tetactory	
	Margar C	ENGINE M	ODEL:	Mangon Aircraft, Inc.	DATE: 05 December, 2013
-	(fo here	REG. NO: 5	5058L	501 Sky Ranch Drive	A/C TSN: 2143.64 ENG TT:
		WORK OR	DER: 14498 Ph	Petaluma, CA 94954-3908 Phone: (707) 765-1848	TACH 2143.64
		Engine			
		Oil change ground ope	d. Oil pressure and suc erated, leak check good	tion screens inspected and cleaned, nothing found. Engine Starter bendix cleaned and lubricated with Silicone lube	wished and serviced with Phillips 20W-50XC. Engine s.
				0 /	
-			5 December, 2013	SIGNED: Dad Ma	Work Order: 14498
		DATE: 05			The state of the s
		DATE: 05		David Mongon, A&P: 3592237	Printed by EBis 3 (datcomedia.com)
		ENGINE MODEL		David Mengon, A&P. 3582237 Mangon Aircraft, Inc.	Printed by Ethis 3 (datcomedia.com) DATE: 02 September, 2014 AC TSN: 2166.41

ENGINE MODEL: ENGINE S.N: REG. NO: 5058L WORK ORDER: 14498	Mangon Aircraft, Inc. 501 Sky Ranch Drive Petaluna, CA 94954-3908 Phone: (707) 765-1848	DATE: 05 December, 2013 AVC TSN: 2143.64 ENG TT TSMOH TACH: 2143.64
Engine Entries Oil changed. Oil pressure and suc ground operated, leak check good	ction screens inspected and cleaned, nothing found. Engine d. Starter bendix cleaned and lubricated with Silicone lube.	washed and serviced with Phillips 20W-50XC. Engine
DATE: 05 December, 2013	SIGNED: David Mary David Mary 2592237	Work Order: 14498 Printed by EBis 3 (datcomedia.com)
ENGINE MODEL: AEIO-360-H1A ENGINE SN. RI-11294-51A REG. NO: 5058L WORK ORDER: 14763 Engine Entries	Mangon Aircraft, Inc. 501 Sky Ranch Drive Petaluma, CA 94054-3508 Phone: (707) 765-1848	DATE: 02 September; 2014 ACTSN: 2106.41 ENG TT: 413.21 TSMOH: 413.21 TACH: 2166.41
detail of FAR 43.13, Appendix D et e 10 torqued and saffield. Oil serviced with Pl synd'd checked satisfactory, Spark Pulg Checked no leaks Engine forward lift adel clamps to prevent chafing Ignitio	with those items extracted from the manufactures inspection go 0 hour interval. Oil drained, oil filter and oil screen removed as sulpice 20x0000 Bitts. Compression test: Cylinder 1-70700, 2 is cleaned, gapped inspected and notated. Fuel system press, hopk in indexed to face at to prevent challing on cowling	nd inspection on reliable particles. Oil filter installed, 77760, 3-7760, 4-7780. Memory and received, more checked, no leaks. Exhaust system pressure prison wires for bottom cylinders 2 and 4 secured with bested with high tension lead tector. Test and function received with the control of
ANNUAL CERTIFICATION AND WAS I	BEEN INSPECTED IN ACCORDANCE WITH THE REQUIRM DETERMINED TO BE IN AIRWORTHY CONDITION.	ENTS OF A 100-HOUR INSPECTION FOR AN Work Order: 14763
X X	SIGNETO SOM POLONNELLY ohn O Colodi, ASP. 3564328 IA	Printed by EBis 3 (datcomedia.com)

DATE	IN SERVICE	SINCE OVERHAUL	METER TIME	SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK	
10/7/15	462do 72215	462.06 26	-	T.a. M Aviation 1461 S. State Street Ukiah GA 95482 [707] 462-1417	
			Annual Compr Change noted. 8 quar Cleane P/N BA AD's c line i Inspect	Model: AEIO-360-H1A Serial No.: RL-11294-51A inspection completed. essions as follows: #1 75/80, #2 77/80, #3 77/80, #4 76/80 ed oil and cleaned oil screen filter with no metal debit Tightened and safetied oil drain cap. Serviced engine with a Aeroshell 15W-50 oil. Tightened oil temperature probed and gapped spark plugs. Installed new intake air filter a-8103-1. Engine run-up performed, with no leaks noted. A Checked through 2015-19. C/W A.D.2011-26-04 fuel injection in the complete complete in the complete complete in the complete compl	nris - the e. er
			-	To H Aristian Mot S, State Street Brian 6a 354427 1970 495-1467	
•			P/N 611 engine	NS058L Tach: 2230.78 c oil and cleaned oil screen. Serviced engine puarts Aeroshell 15W-50 oil and a Lycoming 173 oil screen housing gasket. I certify that this is in an airworthy condition pertaining to and gard to the work performed.	
	-		-	To Il Aviation 1401. State Street	



1 is	METER TIME	SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK	
gine ing at th at th		TOTALS brought forward from previous page	
12 Mainten 13 Mainten 13 Mainten 14 Mainten 15 M	servo P/ 2524752 firewall. P/N BA- Adjusted noted. A line insp	N5085L Tach: 2292.05 TTSN: 538.85 TSO: 499.49 Model: AEIO-360-H1A Serial No.: RL-11294-51A Inspection completed. Inspection as follows: #1 70/80, #2 70/80, #3 76/80, #4 70/80. If oil and cleaned oil screen filter with no metal debris noted. If engine with 8 quarts Phillips 20W-50XC oil. Removed old fuel Inspection: N: 2524752-7 S/N: 70176905, installed overhauled fuel servo P/N: Inspection: Total and the service of the ser	

M	T/7/19 Change with 8 q P/N 611	with reg	annual in	that this engine has been inspected in accordance with an inspection and was determined to be in an airworthy condition. Michael Whetzel, A&P2692702I/A
1/27/201	591.5	523.1	2344.8	compression fest Results #/ 70/80 #2 70/80 #3 75/80 #4 74/80 complied with AD2015-19-07 dated 11/3/15 by Dospection fuel projection lines for proper Routing security + conductor next due 2454.8 THUI POST DOSPECTION Ground performance Pur Coak + systems vs satisfactory I certify that this ED5/WC has been inspected In accordance with a(1) ANNUAC and found to be in An airworthy condition this time and date. Time 2344.8 TH Date 1/27/2021 KYLEGABEL A&P2885867IA
				SUB-TOTALS this page

DATE TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
- 1/02/		Lausensk's	TOTALS brought forward from previous page
1/2-22 23	62 608	L. Gas	Comp# 17/00 # 2 7/80
-11-1001 20	es eso		#3174 # 4 7/80 Dil
			Courced DK dais Del Fill
			WY 20-50 CWAD 7011-76-04
			I certify this Alveralt Engine has been Inspected IAW an 100 hr/Append
			Airworthy Condition.
			Eric O. Sawyer A&P 3521645 @
- Jahan			ace
			Fuller Aircraft Services
N X		822 E. Sant	a Maria St. Hangar #9 Santa Paula, CA. 93060
			ENGINE LOGBOOK ENTRY REG. #: N5058L
			Bellanca: 8KCAB S/N: 558-79
		Lyco	oming: AEIO-360-H1A S/N: RL-11294-51A
			Tach Time: 2384.97
			creen, found normal, cleaned & reinstalled screen with new gasket P/N SL61173 & C 20W-50. Performed ground run/leak check, found satisfactory.
The with	aircraft, airframe current regulatio	engine, prope ns under the F	eller or appliance identified above was repaired and/or inspected in accordance ederal Aviation Administration and is approved for return to service.
Glen	n Fuller	111	A&P 3493937 July 21, 2023

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
2)19/2024/240	2401.6	608.9	2401.6	compression test Results
				88/30 FT 08/20 ET 08/20 C# 08/20 /#
				complied with 1000015-19-07 date / 11/3/2015 by
Harris				Inspection fuel Injection lines for Routing
	100	Service Services	Philipping	Socu: ty + cond (tion west due 25/16 TRAY
			Comme Ge	cleaned + flow checked fuel vozzels
			The state of	Replaced spark plugs with New Unison
				UREM 38E s.
				Surviced 875 Phillips 20W-50 Xe sil
				Removed starter. Disasson blog and deans
				Shoft & Bendix drive Reassemble/&
				Rens talled, oplox.
				Past Inspection Ground performance Run 1
				leak V + systems vs satisfactory,
				Feertify that this Engine has been inspected
				In accordance with a(n) ANNUAC and found to be in An airworthy condition this time and date. Time 24016 TTA Date 2 19 2029
				KYLE GABEL A&P2885867IA

Sent from my iPhone